

**MONUMENT RECORD**  
**State of Indiana - County of Monroe**

**Section: 22**


**Township: 9 North**

**Range: 1 West**

**Corner ID: Blm Q-17**

**Monument Description & Remarks:** Found 5/8" Rebar with "SNA Inc LS9300019" cap at SE corner of section. Rebar was 0.65' out of ground. Griffy Creek approximately 120' south of rebar.

**References on file in the County Surveyor's Office:** Lake Griffy Boundary Survey completed by Jess Gwinn, R.L.S. No. 9300019, dated May 4, 1998.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 20-1-2 of the Indiana Code; and the above data is given under my hand and seal this 16th day of November, 1998.

*Kevin P. Enright*

Administered by Surveyor Review Board

